

**TEP Rocky Mountain LLC
GM 14-27
Location #335306**



View from entrance to location



**View from location entrance of lease road and
production facility**

**TEP Rocky Mountain LLC
GM 14-27
Location #335306**



SouthEast corner location erosion

SouthEast corner trap erosion and sediment fill

**TEP Rocky Mountain LLC
GM 14-27
Location #335306**



Sediment migration and erosion



Erosion underneath waddle

**TEP Rocky Mountain LLC
GM 14-27
Location #335306**



Sediment migration on separator pad



Northwest corner erosion from location