

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/22/2023

Submitted Date:

03/22/2023

Document Number:

696304726

**FIELD INSPECTION FORM**

Loc ID 426841 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10773  
Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC  
Address: 5251 DTC PKWY STE 950  
City: GREENWOOD State: CO Zip: 80111

**Findings:**

- 14 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Sydney		ssmith@fundareresources.com	Regulatory

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426812	WELL	SI	08/01/2017	OW	123-34787	Wolf 36-3624H	SI

**General Comment:**

This is a Field Inspection. Any Corrective Actions from Interim Reclamation and Stormwater Inspection 696105632 dated 12.06.2022 are STILL applicable ant Corrective Actions remain the SAME.

<b>Location</b>			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	From Inspection 696105632, dated 12.05.2022. No emergency contact information posted; Sign not legible at treater/building. Refer to attached inspection photos.		
Corrective Action:	Install sign to comply with Rule 605.g		Date: 01/06/2023
Type	BATTERY		
Comment:	Sign at Entrance still shows Whiting as Operator. See photos		
Corrective Action:	Install sign to comply with Rule 605.a.		Date: 04/24/2023
Type	TANK LABELS/PLACARDS		
Comment:	Tank Battery Sign still shows Whiting as Operator		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 04/24/2023
Type	WELLHEAD		
Comment:	Sign still shows Whiting is the Operator; see photos		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 04/24/2023
Emergency Contact Number:			
Comment:	No Updated Fundare 24 Emergency Contact Number or Info. Posted on Site		Date: 04/24/2023
Corrective Action:	Install sign to comply with Rule 605.a.		Date: 04/24/2023
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	From Inspection 696105632 dated 12.06.2022. Unused pipe and fittings located on northwest corner of location. See photos.		
Corrective Action:	Comply with Rule 606		Date: 12/14/2022
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		

Comment: TA Wellhead		Date:
Corrective Action:		Date:
Type: Vertical Heater Treater	# 1	
Comment:		Date:
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: Appears to be plumbed to surface		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		Date:
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:		Date:
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares berm with the Crude Oil Tanks		Date:		
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLS	STEEL AST		40.800530,-103.929040
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 426812 Type: WELL API Number: 123-34787 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. All Signs on Location STILL show Whiting Oil and Gas. Unused Pipes and Fittings where ECD and Flare have been removed. Refer to I.R. and Stormwater Inspection 696105632 dated 12.06.2022 for Weeds on Location</a>	petrie	03/22/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403353254	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6058856">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6058856</a>
696304727	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6058832">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6058832</a>