


Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34NESW

Location #: 334570



Location Overview: Location is located in a 411 a. internal buffer zone and approximately 466 yards from the Colorado River.

Section/Township/Range: 34 6S95W

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34NESW

Location #: 334570



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34NESW

Location #: 334570



Photo #9389 Location lacks stabilization.



Photo #9390 Location lacks stabilization.

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34NESW

Location #: 334570



Photo #9392 Location lacks stabilization.



Photo #9396 Insufficient tracking BMP at entrance to location.

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34NESW

Location #: 334570



Photo #9403 Rill erosion on berms.



Photo #9404 Berm degradation. Sediment encroaching on secondary containment.

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34NESW

Location #: 334570



Photo #9406 Run on to location is not being controlled.



Photo #9407 Run to location is not being controlled.

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34NESW

Location #: 334570



Photo #9409 Run on to location is not being controlled.