

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-27 pad

Location ID: 335128



Photo # 3552 From entrance to location



Photo # 3553 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-27 pad

Location ID: 335128



Photo # 3554 Location



Photo # 3555 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-27 pad

Location ID: 335128



Photo # 3556 Location



Photo # 3558 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-27 pad

Location ID: 335128



Photo # 3562 Unmarked deadman



Photo # 3566 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 522-27 pad

Location ID: 335128



Mar 28, 2023 at 11:17:29 AM
CO



Mar 28, 2023 at 11:19:29 AM

Photo # 3576 Chemical containment full/Failure to maintain chemical BMP (located on remote location – CLOUGH RMV 226-27 pad location # 324161)

Photo # 3580 Chemical containment full/Failure to maintain chemical BMP (located on remote location – CLOUGH RMV 226-27 pad location # 324161)