

# Inspection Photos

API: 071-08799

Operator: OGRIS OPERATING LLC

Inspection Date: 3/29/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08799 | Date: 3/29/2023

## Inspection Photos



**Photo 1.** Facing toward the access road. There are signs of erosion from stormwater not diverted toward the culvert. Grading should be performed to direct stormwater toward the culvert.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08799 | Date: 3/29/2023



## Inspection Photos



**Photo 2.** Facing north toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08799 | Date: 3/29/2023

## Inspection Photos



**Photo 3.** Facing toward the fill slope which needs to be reseeded and stabilized. There are also noxious weeds in this area (Canada thistle) which will need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08799 | Date: 3/29/2023