

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 3795 From entrance to location



Photo # 3796 From entrance to upper tier of location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 3797 Location



Photo # 3807 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 3808 Location



Photo # 3800 Unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 3810 Meter calibration info not conspicuously posted



Photo # 3811 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 3798 Sediment Trap needs maintenance (upper tier of pad, NW edge of pad across from wellheads.)



Photo # 3802 Rill erosion & transport of sediment off location (upper tier of pad NW edge of pad past sediment trap)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 3803 Rill erosion & transport of sediment onto location (upper tier NE side of pad)



Photo # 3804 Rill erosion & transport of sediment onto location (upper tier east side of pad)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 3805 Rill erosion & transport of sediment off location (upper tier of pad, SW area)



Photo # 3813 Erosion & transport of sediment onto location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 3814 Erosion/transport of sediment off location/insufficient BMP's



Photo # 3816 Erosion/transport of sediment off location/insufficient run off controls/BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 230-28 pad

Location ID: 335151



Photo # 3820 Rill erosion & transport of sediment off location onto lease road/insufficient BMP's



Photo # 3818 Rill erosion & transport of sediment off location onto lease road/insufficient BMP's