

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2023

Submitted Date:

03/30/2023

Document Number:

708300242

FIELD INSPECTION FORM

 Loc ID 334450 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:23 Number of Comments1 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, LARAMIE		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290616	WELL	PR	11/13/2012	GW	077-09289	NORTH VEGA 27-341	PR
291284	WELL	PR	02/01/2022	GW	077-09323	DLC 27-241	PR
291350	WELL	PR	07/10/2007	GW	077-09322	DLC 27-331	PR
291353	WELL	PR	07/10/2007	GW	077-09321	DLC 27-441	PR
291755	WELL	PR	08/07/2007	GW	077-09371	DLC 27-244	PR
291763	WELL	PR	08/07/2007	GW	077-09375	DLC 27-234	PR
291764	WELL	PR	08/07/2007	GW	077-09374	DLC 27-344	PR
291765	WELL	PR	08/07/2007	GW	077-09373	DLC 27-444	PR

General Comment:[COGCC Inspection Report Summary](#)

On 3/30/2023 at approximately 11:30, Compliance Inspector Matthew Morris conducted an on-site inspection at LARAMIE ENERGY LLC, NVega/1B Pad at Location ID #334450 in Mesa County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Cut slope erosion causing run-on to location
- 2) Lease road degradation from snow plow causing transport of sediment and lack of stabilization
- 3) Lease road lacks stabilization with inadequate tracking BMP in place to minimize sediment transportation

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Pipe rail guards		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Pipe rails		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 8		corrective date
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	Pressure transducers located on Bradenheads		
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	290616	Type:	WELL	API Number:	077-09289	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	291284	Type:	WELL	API Number:	077-09323	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	291350	Type:	WELL	API Number:	077-09322	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	291353	Type:	WELL	API Number:	077-09321	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	291755	Type:	WELL	API Number:	077-09371	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	291763	Type:	WELL	API Number:	077-09375	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	291764	Type:	WELL	API Number:	077-09374	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	291765	Type:	WELL	API Number:	077-09373	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Eroded BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			Inadequate BMP to prevent tracking
		Berms				
		Culverts				
		Ditches				
		Other	Fail			Inadequate tracking BMP
		Gravel	Fail			Inadequate BMP to prevent tracking
Berms						
Other	Fail					Cut slope eroding onto location

Comment:
 1) Cut slope erosion causing run-on to location
 2) Lease road degradation from snow plow causing transport of sediment and lack of stabilization
 3) Lease road lacks stabilization with inadequate tracking BMP in place to minimize sediment transportation
 Unable to inspect all BMPs due to snow cover

Corrective Action: **Comply with Rule 1002**

Date: 04/14/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300247	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6067692