

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2023

Submitted Date:

03/27/2023

Document Number:

696204798

FIELD INSPECTION FORM

Loc ID: 315810 Inspector Name: Trujillo, Aaron On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 9 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 16700
 Name of Operator: CHEVRON USA INC
 Address: 760 HORIZON DRIVE STE 401
 City: GRAND JUNCTION State: CO Zip: 81506

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Sanford, Anita		Anita.Sanford@scoutep.com	Rangely Field
Patterson, Chris		Chris.Patterson@scoutep.com	
,		RangelyRegulatory@scoutep.com	Rangely Field
Olson, Andrew		andrewolson@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
315810	LOCATION	AC			-	A C MCLAUGHLIN-62N103W 14NWSE	RI

General Comment:

On 3/24/2023, Reclamation Specialist Trujillo inspected Chevron USA's A C MCLAUGHLIN 59AX location in Rio Blanco County, Colorado.

Well records show Chevron USA Inc as the designated Operator for the Location. Form 9(s) 402891516 transferring the Location/Well from Chevron to Scout Energy management currently "in process". Chevron remains the Operator responsible for the management of the Location until the Form 9 is approved.

The following compliance issues were observed during this inspection:
 -Stormwater: Missing or insufficient tracking BMPs on working pad and access road

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

See inspection #696204791 and #696204758 regarding tracking issues onto Hwy. 64.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
	Type Main		
comment:	See "Storwwater". Reclamation Specialist was unable to access Locations beyond the A C MCLAUGHLIN 59AX due to poor road conditions. Operator has failed to maintain access road(s) in a manner to accommodate all weather access, in accordance with Rule 603.I		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
	Type OTHER		
Comment:	Location		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 315810 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____
 Comment

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: See "Stormwater" under COGCC Comments.						
Corrective Action: Comply with Rule 1002.f.(2)						Date: 03/29/2023
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
STORWMATER COMMENTS It was observed in this inspection that stormwater, tracking, and erosion control BMPs are missing or insufficient throughout the Location, and access road: -BMPs to stabilize, as well as to minimize degradation, tracking and offsite sediment transport are missing or insufficient at the Location, as well as at the access road leading to and beyond the Location; erosion degradation, tracking and sediment transport observed. Access road does not appear to be adequately engineered to manage runoff and to minimize degradation, tracking and sediment transport; refer to inspections #696204791 and #696204758 regarding tracking/sediment transport onto Highway 64.	trujilloam	03/27/2023
Stormwater and related access road issues appear to be prevalent throughout the entire Field.	trujilloam	03/27/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403357239	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6063477
696204799	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6063456