

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/04/2023

Submitted Date:

04/04/2023

Document Number:

707900966

**FIELD INSPECTION FORM**
 Loc ID 319046 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Mattox, Jennifer	303-692-3144	jennifer.mattox@state.co.us	Oil and Gas Inspections and Compliance
Leonard, Mike		mike.leonard@state.co.us	
,	303-825-4822	cogcc@kpk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242767	WELL	PR	04/05/2002	OW	123-10558	ANDERSON 1	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road has deep ruts and and holding water due to high truck traffic and weather conditions		
Corrective Action	Comply with 1002 storm water BMP.	Date:	05/04/2023

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate sign is starting to fade may need to be replaced in near future.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>				corrective date
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	
Type: Vertical Separator	# 1			
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device	# 3			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 2			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 5			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with crude oil tanks				
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:	Gauge hatch open or not sealed.				
Corrective Action:	Close and seal gauge hatches when not accessing tank per Rule 608.a.(9).				
Date:	04/05/2023				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Insufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Wells Served By Facilities Above

API Number
123-23790
123-23792
123-10558
123-23789

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	YES		
Comment:	At time of inspection pumper was venting through the gauge hatch on 300 BBL crude oil tank. Gas being vented or flared during non-upset condition without prior approval from COGCC.		
Corrective Action:	Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare. Comply with rule 903		
Date:	04/05/2023		

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 242767 Type: WELL API Number: 123-10558 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 02/27/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary

On Monday April 4, 2023 at approximately 2:15PM, I, Inspector Randy Silver, conducted an on-site inspection in response to complaint Doc #403360904.

Location: Anderson #1 Battery

Operator: KP Kauffman

GPS: 40.268979, -104.913684

County: Weld

While there, I observed a production facility.

During this inspection the following possible compliance issues were observed:

Venting: Rule 903 Corrective action date of 4-5-23

Gauge hatch: Rule 608 Corrective action date of 4-5-23 See photos

Weather conditions: Clear

As I pulled up to location pumper was venting gas through Crude oil tank. Gauge hatch was open.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

silverr

04/04/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707900967	pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6071287">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6071287</a>
707900968	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6071288">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6071288</a>