

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2023

Submitted Date:

04/04/2023

Document Number:

708200084

FIELD INSPECTION FORMLoc ID 460414 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	
ZUNIGA, ERICA		ericazuniga@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
460414	LOCATION	AC			-	LD07-01 MULTI	RI

General Comment:

This is a follow-up inspection to Field Inspection Report (Doc #696105699) and Operator submitted FIRR (Doc #403313348) to document corrective action compliance.

Location

Lease Road:			
Type	Other		
comment:	North end of facility/production area has heavy rutting. Refer to attached inspection photos.		
Corrective Action		Date:	

Overall Good: ☐

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	DEBRIS		
Comment:	Operator submitted one photo of debris removal in the FIRR (photo doc #403350673). However, additional debris was observed throughout the interim areas and has the potential to migrate off location. Refer to attached inspection photos.		
Corrective Action:	Comply with Rule 606 and remove/dispose of debris from location, including any debris that might have migrated off location.	Date:	04/11/2023
Type	OTHER		
Comment:	Tank battery at south end of location appears to have been cleaned and oily waste disposed of. Refer to attached inspection photos.		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	It appears the operator has performed the corrective action and removed tumbleweed debris from the location. During this inspection, high winds were encountered and tumbleweed debris was starting to accumulate again; Operator shall continue to manage the location and control/dispose of weedy debris.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 460414 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708200101	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6072312