

FORM  
INSPRev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/29/2023

Submitted Date:

03/29/2023

Document Number:

707900930

### FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
318122 \_\_\_\_\_ Silver, Randy \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: \_\_\_\_\_ 46290 \_\_\_\_\_  
Name of Operator: KP KAUFFMAN COMPANY INC \_\_\_\_\_  
Address: 1700 LINCOLN ST STE 4550 \_\_\_\_\_  
City: \_\_\_\_\_ DENVER \_\_\_\_\_ State: \_\_\_\_\_ CO \_\_\_\_\_ Zip: \_\_\_\_\_ 80203 \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 8 \_\_\_\_\_ Number of Comments  
2 \_\_\_\_\_ Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	<a href="#">All Inspections</a>
Leonard, Mike		mike.leonard@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240646	WELL	PR	01/01/2023	OW	123-08434	COSSLETT A 5	SI

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	A Dequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	BMP: there are no BMP's on disturbed pipeline area between Cosslett 5 and Cosslett 1 and 6 tie in. Pipeline is settling in spots due to no soil stabilization and construction area.		
Corrective Action:	Comply with rule 1002 series.	Date:	04/05/2023
Type	TRASH		
Comment:	Pipe and metal on well site.		
Corrective Action:	Comply with rule 606	Date:	04/05/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 240646 Type: WELL API Number: 123-08434 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: At time of inspeciton Flow line valves are in the closed position. Production records show well has produced once in 11 months.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 08/05/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday March 29, 2023 at approximately 11:34AM, I, Inspector Randy Silver, conducted an on-site inspection.                      Location: Cosslett A #5                      Operator: KP Kauffman                      API#: 123-08434                      County: Weld                      While there, I observed a Shut in well site and pipeline excavation.                      During this inspection the following possible compliance issues were observed:                      Trash: Rule 606 Corrective action date of 4-5-23 see photos                      BMP's: Rule 1002 Corrective action date of 4-5-23 see photos                      Weather conditions: Clear                      At time of inspection there are no BMP's on entire area disturbed by pipeline repairs between well head and main line of Cosslett 1 and 6. Pipeline ditch is settling due to no soil stabilization.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	silverr	03/29/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403359559	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6065524">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6065524</a>
707900931	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6065519">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6065519</a>