

Inspection Photos
Location Name: YC-2
API #: 083-06374



11/2/22 inspection photo. Opening in cellar grate, standing fluid,



4/3/23 photo showing grate opening still present.

Inspection Photos
Location Name: YC-2
API #: 083-06374



Crimped culvert 11/2/22 inspection photo



4/3/23 photo, culvert

Inspection Photos
Location Name: YC-2
API #: 083-06374



Crimped culvert repaired. No inlet protection, soft erosive soils



Culvert outlet, no outlet protection

Inspection Photos
Location Name: YC-2
API #: 083-06374



Looking east and uphill at ditch east of culvert



East side of roadway east of YC-2 looking east and uphill