

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2023

Submitted Date:

04/05/2023

Document Number:

700300553

FIELD INSPECTION FORM

Loc ID 313575 Inspector Name: LABOWSKIE, STEVE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LP
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		CO2Source_Regulatory@kindermorgan.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224519	WELL	PR	03/08/2018	CO2	083-06584	YC 4	PR

General Comment:

Compliance supervisor Steve Labowskie and SW Compliance specialist Curtis Patillo conducted follow-up inspection of stormwater corrective actions on access road doc# 70030494 after operator submitted FIRR indicated corrective actions were complete.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:	AVO did not observe any gas leaks. Too windy for FLIR survey at tinme of inspection.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 224519 Type: WELL API Number: 083-06584 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			
		Ditches	Pass			
Compaction	Pass					
		Gravel	Pass			
Gravel	Pass					

Comment: Existing BMP of ditches cleared, some areas filled in with fresh road base. Road base filled in erosion channel across road cited in previous inspection. Road base not fully compacted/stabilized. See photos of shovel test. Steeper sections of ditch appear prone to allow for sediment transport to low areas without additional BMPs, such as but not limited to check dams, aroring, sediment traps. It's understood that operator is working with surface manager to about longer term solutions that could require additional disturbance, however, maintenance of areas already disturbed not completed.

Corrective Action: Comply with 1002.f by minimizing erosion and transport of sediment off site by implementing additional BMPs, stabilize new loose materials.

Date: 04/01/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300555	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6073339