

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/05/2023

Submitted Date:

04/05/2023

Document Number:

702401775

FIELD INSPECTION FORMLoc ID 318557 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241595	WELL	PR	01/01/2023	GW	123-09384	PAUL 1	SI

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	sign has old operator information and needs to be updated		
Corrective Action:	Comply with Rule 605.d	Date:	05/05/2023
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	card indicates current calibration		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment: automation		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT		,
Comment:					Date:
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	40 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: shares containment with crude tank				Date:	
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	STEEL AST		40.111320,-104.340270
Comment:					Date:
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	210 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
123-09384		

Venting:

Yes/No	NO
--------	----

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	241595	Type:	WELL	API Number:	123-09384	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="SI"/>									
Corrective Action: <input type="text"/> Date: _____									
BradenHead									
Date of Last Brhd Test: <input type="text" value="01/26/2023"/> Annual Brhd Completed? <input type="text" value="Yes"/>									
Last Brhd Test Results Initial Surf Csg Pressure: <input type="text" value="0"/> Fluid Type: _____									
End Surf Csg Pressure: <input type="text" value="0"/>									
Comment: <input type="text"/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 4-5-2023 at approximately 1245 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: KP Kauffman</p> <p>Location name: Paul 1</p> <p>API #05-123-09384</p> <p>County: Weld</p> <p>Weather: Clear.</p> <p>Location: Dry.</p> <p>While there, I observed a wellsite and tank battery, SI at the time of inspection.</p> <p>During this inspection, I observed the following possible compliance issues:</p> <p>605.d WH sign: sign has old operator information and needs to be updated, CA date 5/5/2023.</p> <p>See attached photos.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	04/05/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702401776	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6073417