

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-20 Pad

Location ID: 335217



Apr 4, 2023 at 9:42:44 AM
CO

Photo # 4143 From entrance to location



Apr 4, 2023 at 9:42:47 AM
CO

Photo # 4144 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-20 Pad

Location ID: 335217



Photo # 4145 Location



Photo # 4146 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-20 Pad

Location ID: 335217



Photo # 4166 Location




Photo # 4167 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-20 Pad

Location ID: 335217



Photo # 4147 Meter calibration info not conspicuously posted




Photo # 4148 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-20 Pad

Location ID: 335217




Photo # 4167 RMV 206-20 wellhead sign not conspicuously posted



Photo # 4117 Lack of stabilization/Insufficient tracking BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-20 Pad

Location ID: 335217



Apr 4, 2023 at 10:08:38 AM
CO

**Photo # 4178 Lack of stabilization/Insufficient tracking
BMP's**



Apr 4, 2023 at 10:06:13 AM
CO

**Photo # 4172 Lack of stabilization/Insufficient tracking
BMP's**