

**Chevron U.S.A. Inc.
A.C. Mclaughlin 44A
Location #311854**



West side access entrance to location



Looking North

**Chevron U.S.A. Inc.
A.C. Mclaughlin 44A
Location #311854**



Unmarked anchor on SE corner



Location lack of stabilization



**Chevron U.S.A. Inc.
A.C. McLaughlin 44A
Location #311854**



Faded chemical tank label needs replaced



Faded chemical tank label needs replaced

**Chevron U.S.A. Inc.
A.C. Mclaughlin 44A
Location #311854**



Location lack of stabilization



Access road from the East into location