

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2023

Submitted Date:

04/04/2023

Document Number:

708200084

FIELD INSPECTION FORM

Loc ID: 460414 Inspector Name: Edwardson, Dylan On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
ZUNIGA, ERICA		ericazuniga@chevron.com	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
460414	LOCATION	AC			-	LD07-01 MULTI	RI

General Comment:

This is a follow-up inspection to Field Inspection Report (Doc #696105699) and Operator submitted FIRR (Doc #403313348) to document corrective action compliance.

Location

Lease Road:			
Type	Other		
comment:	North end of facility/production area has heavy rutting. Refer to attached inspection photos.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Good Housekeeping:

Type	OTHER		
Comment:	Tank battery at south end of location appears to have been cleaned and oily waste disposed of. Refer to attached inspection photos.		
Corrective Action:		Date:	

Type	WEEDS		
Comment:	It appears the operator has performed the corrective action and removed tumbleweed debris from the location. During this inspection, high winds were encountered and tumbleweed debris was starting to accumulate again; Operator shall continue to manage the location and control/dispose of weedy debris.		
Corrective Action:		Date:	

Type	DEBRIS		
Comment:	Operator submitted one photo of debris removal in the FIRR (photo doc #403350673). However, additional debris was observed throughout the interim areas and has the potential to migrate off location. Refer to attached inspection photos.		
Corrective Action:	Comply with Rule 606 and remove/dispose of debris from location, including any debris that might have migrated off location.	Date:	04/11/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 460414 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403365260	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6072317
708200101	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6072312