

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4576 From entrance to location



Photo # 4577 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4578 From entrance to location



Photo # 4579 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4580 Location



Photo # 4581 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4582 Location



Photo # 4584 Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4585 Meter calibration info not conspicuously posted



Photo # 4586 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4587 Debris



Photo # 4588 Debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4589 Rill erosion (East side of location)



Photo # 4600 Rill erosion (East side of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4605 Rip Rap run needs maintenance (SE area of location)



Photo # 4607 Rip Rap run needs maintenance (SE area of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4608 Sediment trap needs maintenance



Photo # 4612 Area coming out of sediment trap needs maintenance/insufficient BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4614 Area coming out of sediment trap needs maintenance/insufficient BMP's



Photo # 4617 Rill erosion & transport of sediment (Multiple spots near rip rap run)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4625 Culvert needs maintenance (on lease road 10-20 yards from entrance to location)



Photo # 4645 Debris (on lease road less than 1/10th of a mile after the CLOUGH 111 pad)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4636 Erosion & transport of sediment off lease road/insufficient BMP's (approximately 1/10th of a mile after the CLOUGH 111 pad)



Photo # 4638 Erosion & transport of sediment off lease road/insufficient BMP's (approximately 1/10th of a mile after the CLOUGH 111 pad)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4639 Erosion & transport of sediment off lease road/insufficient BMP's (approximately 1/10th of a mile after the CLOUGH 111 pad)



Photo # 4640 Erosion & transport of sediment off lease road/insufficient BMP's (approximately 1/10th of a mile after the CLOUGH 111 pad)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4630 Erosion & transport of sediment off lease road/insufficient BMP's (approximately 2/10th of a mile after the CLOUGH 111 pad)



Photo # 4627 Erosion & transport of sediment off lease road/insufficient BMP's (approximately 2/10th of a mile after the CLOUGH 111 pad)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4628 Erosion & transport of sediment off lease road/insufficient BMP's (approximately 2/10th of a mile after the CLOUGH 111 pad)



Photo # 4663 Lack of stabilization/compaction on location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4664 Lack of stabilization/compaction on location



Photo # 4665 Lack of stabilization/compaction on location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 32-21 pad

Location ID: 323916



Photo # 4666 Lack of stabilization/compaction on location