

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4953 From entrance to location



Photo # 4954 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4955 Location



Photo # 4956 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4958 Containment liner needs maintenance



Photo # 4959 Meter calibration info not conspicuously posted

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4960 Meter calibration info not conspicuously posted



Photo # 4961 Stained soils & gravel

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4963 Stained soils & gravel



Photo # 4965 Stained soils & gravel

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4966 Stained soils & gravel



Photo # 4968 Stained soils & gravel

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4989 Stained soils & gravel



Photo # 4971 Unmarked deadman

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4973 Debris

Photo # 4974 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4975 Debris



Photo # Debris

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4977 Debris



Photo # 4978 Debris

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4980 Debris



Photo # 4982 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4983 Debris