

Inspection Photos

API: 055-06105

Operator: OXY USA INC

Inspection Date: 4/10/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06105 | Date: 4/10/2023

Inspection Photos



Photo 1. Facing south along the main road. It appears a vehicle slid off the road causing rutting disturbance that will need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 4/10/2023

Inspection Photos



Photo 2. Facing southeast ascending the hill toward the location. There has been grading performed which has widened the road and pulled up the metal rebar which needs to be removed or repaired and made more visible.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 4/10/2023

Inspection Photos



Photo 3. Facing southeast ascending the hill toward the location. The road has been widened along this area which will create more stormwater impact. Disturbance area of the road should be minimized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 4/10/2023

Inspection Photos



Photo 4. Facing southeast ascending the hill toward the location. Grading has pushed out material into a berm which is creating more of a disturbance and not allowing stormwater to be diverted off the road. There is a long stretch of the road where stormwater will be directed down the road which will cause erosion.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06105 | Date: 4/10/2023

Inspection Photos



Photo 5. Facing northwest toward the compressor facility. There is vehicle ruts in this area that need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 4/10/2023

Inspection Photos



Photo 6. Facing northwest at the location. There is various unused equipment and trash debris stored in this area. The damaged culverts and degraded wattle are now stored in this area and need to be removed. Previous corrective action has not been completed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06105 | Date: 4/10/2023

Inspection Photos



Photo 7. There is bent up metal stored in this area that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 4/10/2023

Inspection Photos



Photo 8. Facing back southeast at the location. The area of equipment storage needs to be reduced and disturbance area reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 4/10/2023

Inspection Photos



Photo 10. Facing back east toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 4/10/2023