

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2023

Submitted Date:

04/12/2023

Document Number:

693600775

## FIELD INSPECTION FORM

 Loc ID 440199 Inspector Name: QUINT, CRAIG On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

2 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**
 OGCC Operator Number: 66190  
 Name of Operator: OMIMEX PETROLEUM INC  
 Address: 2501 HARWOOD ST STE 1238  
 City: DALLAS State: TX Zip: 75201
**Contact Information:**

Contact Name	Phone	Email	Comment
Miller, Wendy	469-676-9376	wmiller@omimexpetroleum.com	
Chambers, Christopher	877-425-4882	kchambers@omimexpetroleum.com	
Clark, Robert	214-808-4126	rclark@omimexpetroleum.com	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Fisher, Jeremy	970-854-4733	jeremy_fisher@omimexgroup.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440197	WELL	SI	08/01/2022	GW	095-06470	Sagehorn 12-34-6-45	SI

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	2 Track through farm ground, no tire tracks.		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign mounted on meter shed		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	Emergency contact number has been disconnected.		
Corrective Action:	Comply with Rulr 605.	Date:	04/10/2023

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Steel panels on ground by wellhead.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Steel panels around meter shed		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 440197 Type: WELL API Number: 095-06470 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut in, No production since 8/1/2022, Chart has not been changed since 10/8/2022.

Corrective Action: Submit Production reports and Form 4 well status.

Date: 04/10/2023

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693600776	Inspection Photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079979">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079979</a>