

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2023

Submitted Date:

04/12/2023

Document Number:

693600777

FIELD INSPECTION FORM

 Loc ID 413180 Inspector Name: QUINT, CRAIG On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

2 Number of Corrective Actions

 Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Operator Information:

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Contact Information:

Contact Name	Phone	Email	Comment
Fisher, Jeremy	970-854-4733	jeremy_fisher@omimexgroup.com	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Clark, Robert	214-808-4126	rclark@omimexpetroleum.com	
Miller, Wendy	469-676-9376	wmiller@omimexpetroleum.com	
Chambers, Christopher	877-425-4882	kchambers@omimexpetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413181	WELL	SI	08/01/2022	GW	095-06261	Mickelson 11-34-6-45	SI

General Comment:

Routine Inspection

Location			
Lease Road:			
Type	Access		
comment:	2 Track through farm ground, No tire tracks on lease road.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by well		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact number has been disconnected		
Corrective Action:	comply with Rule 605		Date: 04/10/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Steel panels on ground by wellhead		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Steel panels around meter shed		
Corrective Action:			Date:
Equipment:			corrective date
Type: Vertical Separator	#		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 0		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 0		
Comment:	Unit has been removed		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 413181 Type: WELL API Number: 095-06261 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut in, Chart was last changed on 10/8/2022, No production reports since 8/1/2022.

Corrective Action: Sub mit production reports and Form 4 status of well. Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693600778	Inspection Photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079980