

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2023

Submitted Date:

04/12/2023

Document Number:

693600787

FIELD INSPECTION FORMLoc ID 336747 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Robert	214-808-4126	rclark@omimexpetroleum.com	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Chambers, Christopher	877-425-4882	kchambers@omimexpetroleum.com	
Fisher, Jeremy	970-854-4733	jeremy_fisher@omimexgroup.com	
Miller, Wendy	469-676-9376	wmiller@omimexpetroleum.com	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278962	WELL	SI	08/01/2022	GW	125-09365	BLED SOE 7-3-5-45	PR

General Comment:

Routine Inspection

Location**Lease Road:**

Type	Access		
comment:	2 Track through farm ground.		
Corrective ActionL		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:	Emergency contact number has been disconnected.	Date:	04/10/2023
Corrective Action:	Comply with Rule 605		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Steel panels around all wellhead equipment		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Battery fenced with wire		
Corrective Action:		Date:	

Equipment:

Type: Prime Mover	# 0		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Flowline from meter run has froze and broke, blowing gas inside meter shed and at T entering the ground. COGCC shut in well due to an active gas leak and was unable to contact operator.		
Corrective Action:	Comply with Rule 608.e.	Date:	04/10/2023
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 2	
Comment:	Elec panel, Cement pad	
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		,
Comment:	210 bbl Fiberglass water tank, missing hatch, Shared berms				
Corrective Action:	Compl with 608.a.(13), Install hatch or install wildlife netting.				Date: 04/10/2023

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		40.435100,-102.364730
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	278962	Type:	WELL	API Number:	125-09365	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Producing but shows that it is shut in, Last production report was July 2022, Last chart change was 1/5/2023.								
Corrective Action:	Submit production reports and Form 4 status of well.							Date:	04/10/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693600788	inspection Photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079985