

KT Resources
DOW 20-22
Location # 316310



location



Well head signage lacking information



KT Resources
DOW 20-22
Location # 316310



location



location

**KT Resources
DOW 20-22
Location # 316310**



Tank battery signage lacking information



Lack of BMP's to prevent sediment migration from location



**KT Resources
DOW 20-22
Location # 316310**



Lack of BMP's to prevent sediment migration from location



Lack of BMP's to prevent sediment migration from location



**KT Resources
DOW 20-22
Location # 316310**



Lack of stabilization/compaction



Access road erosion/ lack of stabilization



**KT Resources
DOW 20-22
Location # 316310**



Access road erosion/ lack of stabilization



Access road erosion/ lack of stabilization



**KT Resources
DOW 20-22
Location # 316310**



Access road erosion



Access road erosion/ lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**KT Resources
DOW 20-22
Location # 316310**



Tracking from access road to lease road



Containment is full



**KT Resources
DOW 20-22
Location # 316310**



Tank labeling is fading



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources