

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 112 Pad

Location ID: 335221



Photo # 5243 From entrance to location



Photo # 5244 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 112 Pad

Location ID: 335221



Photo # 5246 Stained soils & gravel around wellhead



Photo # 5249 Stained soils & gravel



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 112 Pad

Location ID: 335221



Photo # 5250 Stained soils & gravel



Photo # 5253 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 112 Pad

Location ID: 335221



Photo # 5257 Failure to minimize surface disturbance



Photo # 5258 Failure to minimize surface disturbance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 112 Pad

Location ID: 335221



Photo # 5259 Failure to minimize surface disturbance



Photo # 5260 Failure to minimize surface disturbance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 112 Pad

Location ID: 335221



Photo # 5261 Failure to minimize surface disturbance



Photo # 5264 Failure to minimize surface disturbance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 112 Pad

Location ID: 335221



Photo # 5267 Failure to minimize surface disturbance



Photo # 5268 Failure to minimize surface disturbance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 112 Pad

Location ID: 335221



Photo # 5269 Failure to minimize surface disturbance



Photo # 5270 Failure to minimize surface disturbance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 112 Pad

Location ID: 335221



Photo # 5272 Failure to minimize surface disturbance



Photo # 5275 Failure to minimize surface disturbance