

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2023

Submitted Date:

04/17/2023

Document Number:

701006868

FIELD INSPECTION FORMLoc ID 337202 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 100 CRESCENT COURT, SUITE 700

City: DALLAS State: TX Zip: 75201

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heibel, Krystal	303-817-5217	krystal.heibel@state.co.us	
Quint, Craig		craig.quint@state.co.us	
Schure, Kym		kym.schure@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Chambers, Christopher	(214) 549-7215	kchambers@omimexpetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284116	WELL	IJ	04/01/2021	DSPW	125-09914	BOWMAN SWD 3B-28-5-44	AC

General Comment:

Routine UIC Inspection

Location					
Lease Road:					
Type	Other				
comment:	Gravel road off Hwy 385				
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	TANK LABELS/PLACARDS				
Comment:	Stickers on tanks. Metal signs by tanks. Need labeling on all tanks				
Corrective Action:	Install sign to comply with Rule 605.h.				Date: 05/17/2023
Type	WELLHEAD				
Comment:	Lease sign by fiberglass shed at wellhead				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:					
Corrective Action:					Date: _____
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
Lube Oil	Tank	>= 5 bbls			
Comment:	Lube oil in berms around tanks. Inspector can't locate source of lube oil spill. Triplex pump may have leaked some lube oil but doesn't hold a large quantity of oil				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.				Date: 04/18/2023
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	LOCATION				
Comment:	Wire fence around storage yard				
Corrective Action:					Date:
Equipment:					
Type: Compressor	# 1				corrective date
Comment:	Triplex pump in east brown shed				
Corrective Action:					Date:
Type: Ancillary equipment	# 2				
Comment:	Electric panel, filter pots and transfer pump in white building				
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		40.381010,-102.274730

Comment:		Fiberglass 200bbls water tank on west side of tank battery used as overflow tank					
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:		Shared berms					
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	400 BBLS	FIBERGLASS AST		40.381010,-102.274730		
Comment:		2-Green tanks					
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:		Shared berms					
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	4	400 BBLS	STEEL AST		40.381010,-102.274730		
Comment:		4-Tan tanks. Northwest tan tank has rusted holes near the top					
Corrective Action:		Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 04/18/2023	
<u>Paint</u>							
Condition		Inadequate					
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	

Inspected FacilitiesFacility ID: 284116 Type: WELL API Number: 125-09914 Status: IJ Insp. Status: AC**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 5 PSIG Previous Test Pressure _____ MPP _____
(e.g. 30 psig or -30" Hg) Inj Zone: MRSN

TC: Pressure or inches of Hg 0 PSIG Previous Test Pressure _____ Last MIT: 08/03/2017

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: NO

Comment: CASING HAD LIGHT BLOW, DIED IMMEDIATELY. TBG HAD 5 PSIG

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701006870	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084261