

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2023

Submitted Date:

04/12/2023

Document Number:

693600787

**FIELD INSPECTION FORM**

Loc ID 336747 Inspector Name: QUINT, CRAIG On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 66190  
Name of Operator: OMIMEX PETROLEUM INC  
Address: 2501 HARWOOD ST STE 1238  
City: DALLAS State: TX Zip: 75201

**Findings:**

- 9 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Chambers, Christopher	877-425-4882	kchambers@omimexpetroleum.com	
Fisher, Jeremy	970-854-4733	jeremy_fisher@omimexgroup.com	
Miller, Wendy	469-676-9376	wmiller@omimexpetroleum.com	
Leonard, Mike		mike.leonard@state.co.us	
Clark, Robert	214-808-4126	rclark@omimexpetroleum.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278962	WELL	SI	08/01/2022	GW	125-09365	BLEDSOE 7-3-5-45	PR

**General Comment:**

[Routine Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	2 Track through farm ground.		
Corrective Action			Date:

Overall Good:

<b>Emergency Contact Number:</b>		
Comment:	Emergency contact number has been disconnected.	
Corrective Action:	Comply with Rule 605	Date: 04/10/2023

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Battery fenced with wire		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Steel panels around all wellhead equipment		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 0		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Elec panel, Cement pad		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Flowline from meter run has froze and broke, blowing gas inside meter shed and at T entering the ground. COGCC shut in well due to an active gas leak and was unable to contact operator.		
Corrective Action:	Comply with Rule 608.e.		Date: 04/10/2023

Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 0		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		
Comment:	210 bbl Fiberglass water tank, missing hatch, Shared berms				
Corrective Action:	Compl with 608.a.(13), Install hatch or install wildlife netting.				Date: 04/10/2023

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		40.435100,-102.364730
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 278962 Type: WELL API Number: 125-09365 Status: SI Insp. Status: PR

**Producing Well**

Comment: Producing but shows that it is shut in, Last production report was July 2022, Last chart change was 1/5/2023.

Corrective Action: Submit production reports and Form 4 status of well.

Date: 04/10/2023

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403372014	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6080001">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6080001</a>
693600788	inspection Photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079985">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079985</a>