

T9N, R59W

N. 1/4 COR.
SEC. 1, T9N, R59W
FOUND 2 1/2" ALUM. CAP
ILLEGIBLE

NE. COR.
SEC. 1, T9N, R59W
FOUND 3 1/4" ALUM. CAP
L.S. NO. 38285

NW. COR.
SEC. 1, T9N, R59W
SET 2 1/2" ALUM. CAP
P.L.S. NO. 38512

W. 1/4 COR.
SEC. 1, T9N, R59W
FOUND 2 1/2" ALUM. CAP
P.L.S. NO. 28285

E. 1/4 COR.
SEC. 1, T9N, R59W
FOUND 2 1/2" GLO BRASS CAP

SE. COR.
SEC. 1, T9N, R59W
FOUND 2 1/2" GLO BRASS CAP

E. 1/4 COR.
SEC. 12, T9N, R59W
FOUND 2 1/2" GLO BRASS CAP

SE. COR.
SEC. 12, T9N, R59W
FOUND 2 1/2" ALUM. CAP
P.L.S. NO.17492

S. 1/4 COR.
SEC. 12, T9N, R59W
FOUND 3 1/4" ALUM. CAP
P.L.S. NO. 38149

SW. COR.
SEC. 12, T9N, R59W
FOUND 3 1/4" ALUM. CAP
L.S. NO. 38285

W. 1/4 COR.
SEC. 12, T9N, R59W
FOUND 3 1/4" ALUM. CAP
L.S. NO. 38285

SW. COR.
SEC. 1, T9N, R59W
SET 2 1/2" ALUM. CAP
P.L.S. NO. 38512

S. 1/4 COR.
SEC. 1, T9N, R59W
FOUND 2 1/2" ALUM. CAP
P.L.S. NO. 28285

SURFACE HOLE LOCATION: NAD 83
GROUND ELEVATION= 4939.4'
LATITUDE= 40.786594°
LONGITUDE= -103.924172°
LATITUDE= 40°47'11.738"
LONGITUDE= -103°55'27.019"

LANDING POINT: NAD 83
LATITUDE= 40.786690°
LONGITUDE= -103.918514°
LATITUDE= 40°47'12.083"
LONGITUDE= -103°55'06.649"

BOTTOM OF PRODUCTION ZONE: NAD 83
LATITUDE= 40.759146°
LONGITUDE= -103.918164°
LATITUDE= 40°45'32.927"
LONGITUDE= -103°55'05.391"


BOTTOM HOLE LOCATION: NAD 83
LATITUDE= 40.758899°
LONGITUDE= -103.918161°
LATITUDE= 40°45'32.038"
LONGITUDE= -103°55'05.380"

CERTIFICATE OF SURVEYOR:

THIS IS TO CERTIFY THAT THE ABOVE PLAT WAS PREPARED FROM FIELD NOTES OF ACTUAL SURVEYS MADE BY ME OR UNDER MY SUPERVISION AND THAT THE SAME ARE TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. THIS CERTIFICATE DOES NOT REPRESENT A LAND SURVEY PLAT OR IMPROVEMENT SURVEY PLAT AS DEFINED BY C.R.S. 38-51-102 AND CANNOT BE RELIED UPON TO DETERMINE OWNERSHIP.

1/12/23
RANDALL K. FRENCH
PROFESSIONAL LAND SURVEYOR
COLORADO REGISTRATION NUMBER 38512

NOTICE:
ACCORDING TO COLORADO STATE LAW YOU MUST COMMENCE LEGAL ACTION BASED UPON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS AFTER YOU FIRST DISCOVER SUCH DEFECT. IN NO EVENT MAY ANY ACTION BASED UPON ANY DEFECT IN THIS SURVEY BE COMMENCED MORE THAN TEN YEARS FROM THE DATE ON THE CERTIFICATION SHOWN HEREON.



NOTES:

- ▲ INDICATES SECTION CORNER.
- INDICATES CALCULATED CORNER.
- ELEVATION BASED ON NAVD88 (GEOID18).
- BASIS OF BEARINGS DERIVED FROM COLORADO COORDINATE SYSTEM OF 1983, NORTH ZONE.
- ALL MEASURED DISTANCES ARE GRID.
- COMBINED SCALE FACTOR: .99976730 CALCULATED FROM THE N. 1/4 CORNER OF SECTION 1, T9N, R59W.
- OPERATOR: JASON CURNUTT / PDOP = 2.1
- WELL FOOTAGES ARE MEASURED AT RIGHT ANGLES TO THE SECTION LINES.

WELL PAD - TIMBRO 0101

TIMBRO 0112-08H
WELL LOCATION CERTIFICATE
316' FNL & 1897' FEL LOT 2 (NWNE) (SURFACE HOLE LOCATION)
300' FNL & 330' FEL LOT 1 (NENE) (LANDING POINT)
LOCATED IN SECTION 1
300' FSL & 330' FEL (SESE) (BOTTOM OF PRODUCTION ZONE)
210' FSL & 330' FEL (SESE) (BOTTOM HOLE LOCATION)
LOCATED IN SECTION 12
T9N, R59W, 6TH P.M.
WELD COUNTY, COLORADO

VERDAD
RESOURCES
1125 17th Street, Suite 550
Denver, Colorado 80202



CONSULTING, LLC

SHERIDAN OFFICE
1095 Saberton Avenue
Sheridan, Wyoming 82801
Phone 307-674-0609

LOVELAND OFFICE
6706 North Franklin Avenue
Loveland, Colorado 80538
Phone 970-776-4331

DRAFTED BY:	SJM	CHECKED BY:	RKF
DATE DRAFTED:	1/12/23	DATE SURVEYED:	12/12/22
REVISED:		FILE NAME:	22-198