

# Inspection Photos

4/17/2023

Operator: CAERUS PICEANCE LLC #10456

Location #334103

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334103



**Photo 1:** Photo taken from the Location entrance facing north and northeast. Photos examples showing BMPs to stabilize, as well as to minimize erosion, degradation and off-site sediment transport are missing or insufficient; pad lacks stabilization. Tracking controls not observed.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334103



**Photo 2:** Photo taken from culvert along access road. Ponding shows BMPs to allow for proper stormwater discharge at road are missing or insufficient; culvert has not been installed or maintained in accordance with good engineering practices; culvert has been pinched at outlet and filled with sediment; culvert lacks proper armoring at and above the inlet/outlet. 6 foot measuring stick for reference.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334103



**Photo 3:** See comments under photo 2.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334103



**Photo 4:** Photos show sediment transport/deposition due to improper stormwater management. 6 foot measuring stick for reference.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334103



**Photo 5:** Photos examples showing various holes observed throughout the secondary containment liner.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334103



**Photo 6:** Fence appears to only be supported by the gate- many t-post supports observed to be unanchored.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334103



**Photo 7:** Unused t-post improperly stored within secondary containment of battery.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334103



**Photo 8:** Wind indicator safety equipment not in proper functioning condition.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334103



**Photo 9:** Photo taken from the interim areas of the Location. Photo shows areas appear to be progressing towards 1003 standards, though uniform establishment compared to the reference does not appear to have been achieved within many areas of the interim.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334103



**Photo 10:** Photo shows interim areas of the Location that have not achieved uniform vegetative establishment. Addition revegetation activities will likely be required.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334103



**Photo 11:** Adjacent reference area for comparison to the interim areas; reference appears to be an irrigated perennial cropland.