

# Inspection Photos

4/17/2023

Operator: CAERUS PICEANCE LLC #10456

Location #334158

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334158



**Photo 1:** Photos taken from the Location entrance. Photos also examples showing BMPs to stabilize, as well as to minimize erosion, degradation and off-site sediment transport are missing or insufficient; pad lacks stabilization. Tracking controls not observed. 6 foot measuring stick for reference.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334158



**Photo 2:** BMPs at cut slopes along access road are missing or insufficient; erosion degradation evident. Slopes lack stabilization.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334158



**Photo 3:** BMPs at cut slopes along access road are missing or insufficient; erosion degradation evident. Slopes lack stabilization.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334158



**Photo 4:** Weed debris at separator equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334158



Photo 5: Tank battery.





## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334158



**Photo 6:** Wind indicator safety equipment not in proper functioning condition.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334158



April 17, 2023



April 17, 2023

**Photo 7:** Photos examples showing BMPs to stabilize, as well as to minimize erosion, degradation and off-site sediment transport are missing or insufficient; pad lacks stabilization. Tracking controls not observed.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334158



**Photo 8:** Photo examples showing BMPs at access road are missing or insufficient during wet conditions.