

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2023

Submitted Date:

04/21/2023

Document Number:

705000261

**FIELD INSPECTION FORM**Loc ID 320179 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		Regulatory@verdadoil.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202922	WELL	PA	05/12/2022	GW	001-08327	GREEN 1	PA
320179	LOCATION	CL			-	GREAT WESTERN GREEN 1	EG

**General Comment:**COGCC Engineering Integrity Inspection; Flowline Inspection  
Photos uploaded

**Inspected Facilities**

Facility ID: 202922 Type: WELL API Number: 001-08327 Status: PA Insp. Status: PA

**Flowline**

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: COGCC Inspector met with Verdad Resources personnel on location. Well (Green 1) has been plugged and abandoned; cut and cap operations are completed. COGCC form 42 notice of start of plugging operations doc #402999493 received 03/03/2022. Wellhead flowline (OL) has been removed. No flowlines/ risers observed at the (PA) wellhead or facility/ battery areas. The facility/ tank battery has been decommissioned; on location flowlines, tanks and equipment removed. Verdad contract personnel were on location at the time of inspection excavating and removing historically impacted soils. Note: Per communication with Verdad personnel, gas gathering line runs E-W between the Green 1 and Edna 1 (001-08482) wells has been AIP; ends cut below grade sealed and capped. Remediation work is ongoing (historical).

Corrective Action:

Date:

Facility ID: 320179 Type: LOCATION API Number: - Status: CL Insp. Status: EG

**COGCC Comments**

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403374468 received on 04/14/2023: Historic spill discovered during facility decommissioning. Well P&A'd, equipment off site.	maclarej	04/21/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000271	Excavation at facility/ battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6090113">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6090113</a>
705000272	Gas gathering signage and E-W alignment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6090114">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6090114</a>