

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2023

Submitted Date:

04/23/2023

Document Number:

707601127

FIELD INSPECTION FORM

Loc ID 306018 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

19 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284699	WELL	PR	04/01/2022	GW	123-23853	ERICKSON A 8-2	PR

General Comment:

This is a WELL / BATTERY inspection.
Well(s): 1: Producing | PR.
Battery: Active.

Centralized Battery serves 6 Location IDs
(306018, 305967, 305968, 305969, 306012, 330150).
(Well(s): 6: Producing | PR).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	West Crude Oil Tank: NFPA labels, contents / capacity labels are peeling / torn. Need replaced.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire. Surrounded by earth berms.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Gas Sales. Calibration card indicates calibration <= 1 year. Last calibration: 09/27/2022. Active, w/ production.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:	1: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: ON. 1: Separator vapor line combustor(s). Controls separator(s) vapors. Pilots: ON.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	ECD scrubber(s).		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY			
Comment:	Centralized Battery serves 6 Location IDs (306018, 305967, 305968, 305969, 306012, 330150). (Well(s): 6: Producing PR).					
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	3	300 BBLs	STEEL AST		40.505620,-104.573720		
Comment:		Equalizer line(s) connect 2 of 3 crude oil tanks.					
Corrective Action:				Date:			
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:		Shares berms w/ produced H2O vault(s).					
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	3	<50 BBLs	CONCRETE SUMP/VAULT				
Comment:							
Corrective Action:				Date:			
Paint							
Condition							
Other (Content)							
Other (Capacity)	48 Bbls.						
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:		Shares berms w/ crude oil tank(s).					
Corrective Action:				Date:			
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:			Date:				
Flaring:							
Type							
Comment:							
Corrective Action:			Date:				

Inspected Facilities

Facility ID: 284699 Type: WELL API Number: 123-23853 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing | PR.](#)

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/20/2022 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: [No record of Brhd test within last 12 months. Refer to Rule 207. Submit current Brhd test. Comply w/ Rule 207.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 04/20/2023 at approximately 16:37 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: ERICKSON A-66N64W/8NWNE Location ID: 306018 Well Name(s): Erickson A 8-2. API: 123-23853. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 6 Location IDs (306018, 305967, 305968, 305969, 306012, 330150). (Well(s): 6: Producing PR).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/23/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601128	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6090759