

# TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/31NWSE

Location # 323813



Location Entrance – Photo #02455

Wellhead – Photo #02456

# TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/31NWSE

Location # 323813



Separator – Photo #02457



Tank Battery – Photo #02458

# TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/31NWSE

Location # 323813



Open-Ended Load Line – Photo #02459



No Wildlife Protection Equipment – Photo #02461

# TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/31NWSE

Location # 323813



**Lack of Stabilization/Transportation of Sediment –  
Photo #02462**

**Access Road: Lack of Stabilization/Transportation of  
Sediment – Photo #02464**

# TEP ROCKY MOUNTAIN LLC, ARCO-66S96W/31NWSE

Location # 323813



**Access Road: Lack of Stabilization/Transportation of Sediment – Photo #02465**



**Inadequate Vehicle Tracking BMPs – Photo #02466**