

# Inspection Photos

Loc: 312051

Operator: SIMCOE LLC  
LOGOS OPERATING LLC

Inspection Date: 4/16/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast along the access road toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 312051 | Date: 4/16/2023

## Inspection Photos



**Photo 2.** This area along the access road was seeded and hydromulched. The swaled area has straw blanket installed. Seeded areas need to be monitored for vegetation establishment and reseeded if needed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 312051 | Date: 4/16/2023

## Inspection Photos



**Photo 3.** Facing southwest toward the swaled area which has been seeded and stabilized with rip/rap and straw blanket.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 312051 | Date: 4/16/2023

## Inspection Photos



**Photo 4.** Facing southwest at the location. There is vehicle rutting off the access road and across the location that needs to be repaired and reclaimed



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 312051 | Date: 4/16/2023

## Inspection Photos



**Photo 5.** Facing southeast towards the BONDAD 33-9 #22A TA well. All interim reclamation areas will need to be monitored and reseeded as needed to ensure perennial desirable vegetation establishes for long term stabilization.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 312051 | Date: 4/16/2023

## Inspection Photos



**Photo 6.** Facing southeast at the location. There is vehicle rutting across the location that needs to be repaired and reclaimed



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 312051 | Date: 4/16/2023

## Inspection Photos



**Photo 7.** Facing southwest at the west side of the location. This area adjacent to the Florida River has been rock rip/raped. Angular rock was used part of this area which hold together much better than round rock which can become displaced.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 312051 | Date: 4/16/2023

## Inspection Photos



**Photo 8.** West side of the location facing east. This area was seeded and hydromulched. There was some vegetation germination observed however, seeded areas will need to be monitored to ensure the vegetation establishment progresses.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 312051 | Date: 4/16/2023