

Inspection Photos

Loc: 333710

Operator: MARALEX RESOURCES INC

Inspection Date: 4/18/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333710 | Date: 4/18/2023

Inspection Photos



Photo 1. Facing southeast toward the location. The gate has fallen off the hinges and needs to be re hung.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333710 | Date: 4/18/2023

Inspection Photos



Photo 2. There is impacted soil at the wellhead that needs to be cleaned up. This issue previously cited and has not been cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333710 | Date: 4/18/2023

Inspection Photos



Photo 3. There is vehicle rutting and track at the location that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333710 | Date: 4/18/2023

Inspection Photos



Photo 4. There is no labeling on the blue chemical drum which was previously cited.



Inspection Photos



Photo 5. There is a pile of weed debris at the location that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333710 | Date: 4/18/2023