

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2023

Submitted Date:

04/24/2023

Document Number:

693600798

FIELD INSPECTION FORMLoc ID 337926 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------------|--------------|-------------------------------|---------|
| Miller, Wendy | 469-676-9376 | wmiller@omimexpetroleum.com | |
| Chambers, Christopher | 877-425-4882 | kchambers@omimexpetroleum.com | |
| Fisher, Jeremy | 970-854-4733 | jeremy_fisher@omimexgroup.com | |
| Clark, Robert | 214-808-4126 | rclark@omimexpetroleum.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 289691 | WELL | PR | 05/01/2021 | GW | 125-10770 | BLED SOE 2-2-5-45 | PR |

General Comment:

Routine inspection

Location**Lease Road:**

| | | | |
|-------------------|-------------------------------|-------|--|
| Type | Access | | |
| comment: | 2 track through pasture grass | | |
| Corrective Action | L | Date: | |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|---|-------|--|
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted on meter shed door, door laying on the ground. Reinstall door. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|---|--|------------------|
| Comment: | Emergency contact has been disconnected | | |
| Corrective Action: | Comply with rule 605.a | | Date: 04/10/2023 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-----------------------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Steel panels around all equipment | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------------|-----|-------|-----------------|
| Type: Vertical Separator | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|------|--|--|
| Type | | |
|------|--|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|------------|
| Facility ID: | 289691 | Type: | WELL | API Number: | 125-10770 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing, chart has not been changed since 1/16/2023, production reports have not been submitted since July 2022. | | | | | | | | |
| Corrective Action: | Change charts as required, submit production reports, submit form 4 status of well. | | | | | | | Date: | 04/10/2023 |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------------|---|
| 693600799 | Inspection Photographs | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6091503 |