

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2023

Submitted Date:

04/24/2023

Document Number:

702401875

FIELD INSPECTION FORM

Loc ID 318464 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241338	WELL	PR	12/01/2022	GW	123-09127	MARTIN T. HART 2	SI

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Meter box, electric panel, and transformers are not being used, there is no meter on the meter box.		
Corrective Action:	Comply with Rule 603.f/606		Date: 11/30/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:			Date:
Type	OTHER		
Comment:	ancillary equip. has fabricated pipe and round stock		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	electric panel, meter box and transformers		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	electric motor		

Inspected FacilitiesFacility ID: 241338 Type: WELL API Number: 123-09127 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI, Valves closed, electric panel is off and no meter on meter box

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 08/15/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 10/28/2021 at approximately 1210 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Martin T. Hart #2 at API #05-123-09127 in Weld County Colorado. While there, I observed a wellsite. PR at time of inspection, Follow up inspection per Doc # 699302456, 699303120 and 699303825 .</p> <p>During this inspection the following possible compliance issue has been observed, documented, turned over to COGCC Enforcement and are now over 2 years delinquent: 603.f Housekeeping: Meter box, electric panel & transformers are not being used, there is no meter on the meter box and dead weeds are around the equip. CA date 11/30/2020.</p> <p>See attached photos.</p> <p>Location: Dry, Weather: clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report</p>	revasr	04/24/2023