

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 56-21 Pad

Location ID: 335062



Photo # 6010 From entrance to location



Photo # 6011 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 56-21 Pad

Location ID: 335062



Photo # 6012 Location



Photo # 6013 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 56-21 Pad

Location ID: 335062



Photo # 6014 Location



Photo # 6017 Stained soils & gravel



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 56-21 Pad

Location ID: 335062



Photo # 6018 Unmarked deadman



Photo # 6019 Unmarked deadman



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 56-21 Pad

Location ID: 335062



Photo # 6031 Meter calibration info not conspicuously posted



Photo # 6032 Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 56-21 Pad

Location ID: 335062



Photo # 6020 Debris



Photo # 6022 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 56-21 Pad

Location ID: 335062



Photo # 6023 Debris



Photo # 6024 Debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC RMV 56-21 Pad
Location ID: 335062



Photo # 6029 Tank label damaged & some info is missing