

# TEP ROCKY MOUNTAIN LLC, PUCKETT-67S96W/6SWNW

Location # 334811



Location Entrance – Photo #02499



Wellheads – Photo #02501





# TEP ROCKY MOUNTAIN LLC, PUCKETT-67S96W/6SWNW

Location # 334811



Separators – Photo #02508



Wildlife Entry Hazard – Photo #02517

# TEP ROCKY MOUNTAIN LLC, PUCKETT-67S96W/6SWNW

Location # 334811



**No Wildlife Protection Equipment Installed – Photo #02518**



**No Wildlife Protection Equipment Installed – Photo #02519**



# TEP ROCKY MOUNTAIN LLC, PUCKETT-67S96W/6SWNW

Location # 334811



Open-Ended Load Line – Photo #02504



Open-Ended Load Line – Photo #02505



# TEP ROCKY MOUNTAIN LLC, PUCKETT-67S96W/6SWNW

Location # 334811



**Lack of Stabilization – Photo #02500**



**Lack of Stabilization – Photo #02502**



# TEP ROCKY MOUNTAIN LLC, PUCKETT-67S96W/6SWNW

Location # 334811



**Slope Erosion onto Location – Photo #02506**



**Degradation/Transportation of Sediment – Photo #02511**



# TEP ROCKY MOUNTAIN LLC, PUCKETT-67S96W/6SWNW

Location # 334811



**Degradation/Transportation of Sediment – Photo #02507**



**Slope Erosion has Overrun Retaining Wall – Photo #02514**



# TEP ROCKY MOUNTAIN LLC, PUCKETT-67S96W/6SWNW

Location # 334811



**Transportation of Sediment onto  
Location/Encroachment on Equipment – Photo #02515**



**Inadequate Vehicle Tracking BMPs at Location  
Entrance – Photo #02512**



# TEP ROCKY MOUNTAIN LLC, PUCKETT-67S96W/6SWNW

Location # 334811



**Access Road Degradation/Transportation of  
Sediment – Photo #02540**