

# CAERUS PICEANCE LLC, PUCKETT-67S96W/6SWNW

Location # 334977



Location Entrance – Photo #02521



Separators – Photo #02527





# CAERUS PICEANCE LLC, PUCKETT-67S96W/6SWNW

Location # 334977



**Tank Battery – Photo #02522**



**Open-Ended Load Line – Photo #02525**



# CAERUS PICEANCE LLC, PUCKETT-67S96W/6SWNW

Location # 334977



Inadequate Containment Capacity – Photo #02529



Degradation/Lack of Stabilization – Photo #02530





# CAERUS PICEANCE LLC, PUCKETT-67S96W/6SWNW

Location # 334977



**Lack of Stabilization – Photo #02532**



**Inadequate Vehicle Tracking BMPs at Location Entrance – Photo #02536**



# CAERUS PICEANCE LLC, PUCKETT-67S96W/6SWNW

Location # 334977



**Slope Erosion onto Access Road – Photo #02544**



**Slope Erosion onto Access Road – Photo #02546**