

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 314-16 Pad

Location ID: 324148



Photo # 6120 From entrance to location



Photo # 6121 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 314-16 Pad

Location ID: 324148



Photo # 6122 Location

Photo # 6123 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 314-16 Pad

Location ID: 324148



Photo # 6124 Stained soils & gravel



Photo # 6125 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 314-16 Pad

Location ID: 324148



Photo # 6128 Meter calibration info not conspicuously posted



Photo # 6129 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 314-16 Pad

Location ID: 324148



Photo # 6130 Containment liner needs maintenance



Photo # 6133 Containment liner needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 314-16 Pad

Location ID: 324148



Photo # 6135 Containment liner needs maintenance



Photo # 6136 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 314-16 Pad

Location ID: 324148



Photo # 6137 Debris



Photo # 6138 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 314-16 Pad

Location ID: 324148



Photo # 6139 Debris

Photo # 6140 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 314-16 Pad

Location ID: 324148



Photo # 6141 Debris



Photo # 6142 Sediment trap needs maintenance (West side of pad approximately 15-20 ft from tank battery)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 314-16 Pad

Location ID: 324148



Photo # 6144 Erosion & transport of sediment on spur road near entrance to location



Photo # 6145 Erosion & transport of sediment on spur road near entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 314-16 Pad

Location ID: 324148



Photo # 6147 Erosion & transport of sediment on spur road near entrance to location



Photo 6149 Erosion & transport of sediment on spur road near entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 314-16 Pad

Location ID: 324148



Photo # 6151 Erosion & transport of sediment on spur road near entrance to location