

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2023

Submitted Date:

04/25/2023

Document Number:

697602055

**FIELD INSPECTION FORM**Loc ID 323285 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245017	WELL	PA	12/19/2022	GW	123-12812	BEEBE DRAW UPRR 31-9	EI
483684	SPILL OR RELEASE	CL	01/13/2023		-	Beebe Draw UPRR 31-9 O SA	EI

**General Comment:**

This is an Environmental inspection. Any corrective actions from previous inspections or forms that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos are attached to document site conditions.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Good

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type STORAGE OF SUPL

Comment: Extra fencing left on site. Orange construction fencing was left all around the area.Corrective Action: Comply with Rule 606.Date: 05/02/2023Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type OTHER

Comment: Metal excavation fencing. Adequate.

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	245017	Type:	WELL	API Number:	123-12812	Status:	PA	Insp. Status:	EI
Facility ID:	483684	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI

**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil				
Comment	All impacted soil has been hauled offsite.			
Corrective Action				Date:

**Spill/Remediation:**

Comment:	Excavation to remove impacted soil. No groundwater was observed.			
Corrective Action:				Date: _____

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602057	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6092445">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6092445</a>