

Inspection Photos
Simcoe LLC. Evelyn Payne C1
API 067-06904



Photo #1. Overview of well location.



Photo #2. View of erosion on run-downs.

Inspection Photos
Simcoe LLC. Evelyn Payne C1
API 067-06904



Photo #3. Produced water tank with impacted gravel.



Photo #4. Impacted area from produced water tank spill.