

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/25/2023

Submitted Date:

04/26/2023

Document Number:

712700041

FIELD INSPECTION FORM

Loc ID 325728 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 16 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Kosola, Jason		jason.kosola@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215299	WELL	PR	04/24/1987	CBM	067-06904	EVELYN PAYNE C 1	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Present		
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	
Produced Water	Tank	<= 1 bbl	
Comment:	General E&P waste requirements.		
Corrective Action:	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905.a. Contact COGCC EPS staff.		Date: 04/28/2023

In Containment: Yes

Comment: Dark colored impacted area surrounding and immediately down gradient of tank labeled produced water. Clean up impacted gravel. See Photos #3 & #4.

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Cattle panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	6-ft chainlink, 3 sided.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Cattle panel		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Telemetry, cattle panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment:	Wellhead and telemetry.	Date:	
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electrical	Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	3" from seperator.	Date:	
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	3" from wellhead to seperator.	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	OTHER		37.264540,-107.562050
Comment:	Partially buried steel tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Berm is L-shaped.			
Corrective Action:				Date:

Venting:

Yes/No	NO	Date:	
Comment:		Date:	
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 215299 Type: WELL API Number: 067-06904 Status: PR Insp. Status: PR

BradenHead

Date of Last Brhd Test: 08/02/2022 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Other	Pass					See Photo #2.

Comment: Run-downs have been overwhelmed leading to visible erosion and sediment migration off pad location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700052	Wee Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093862