

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2023

Submitted Date:

04/26/2023

Document Number:

697602066

**FIELD INSPECTION FORM**Loc ID 320179 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                    | Comment |
|--------------|-------|--------------------------|---------|
| ,            |       | Regulatory@verdadoil.com |         |

**Inspected Facilities:**

| Facility ID | Type                | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|---------------------|--------|-------------|------------|-----------|---------------|-------------|
| 202922      | WELL                | PA     | 05/12/2022  | GW         | 001-08327 | GREEN 1       | EI          |
| 484200      | SPILL OR<br>RELEASE | AC     | 04/14/2023  |            | -         | Green 1       | EI          |

**General Comment:**

This is an Environmental inspection. Any corrective actions from previous inspections or forms that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos are attached to document site conditions.

Historic spill discovered during facility decommissioning. Well is P&A'd, all equipment off site. Large excavation has begun to address the historical spill.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: None

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | OTHER   |       |            |
| Comment:           | Orange construction fencing has fallen all around the excavation.   |       |            |
| Corrective Action: | Fencing is not in compliance. The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended. | Date: | 05/03/2023 |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |        |       |          |             |           |         |    |               |    |
|----------------------|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 202922 | Type: | WELL     | API Number: | 001-08327 | Status: | PA | Insp. Status: | EI |
|                      |        |       |          |             |           |         |    |               |    |
| Facility ID:         | 484200 | Type: | SPILL OR | API Number: | -         | Status: | AC | Insp. Status: | EI |
|                      |        |       |          |             |           |         |    |               |    |

**Environmental****Waste Management:**

| Type               | Management   | Condition | GPS (Lat) | (Long) |
|--------------------|--|-----------|-----------|--------|
| Oily Soil          |  |           |           |        |
| Comment:           | Large impacted soil stockpile is onsite and has been bermed with soil. No liner under the stockpile has been observed. |           |           |        |
| Corrective Action: |  |           |           | Date:  |

**Spill/Remediation:**

|                    |  |  |  |       |
|--------------------|--|--|--|-------|
| Comment:           | Large excavation to address the spill is underway. Groundwater was observed at about 6 feet. No sheen was seen on the groundwater. |  |  |       |
| Corrective Action: |  |  |  | Date: |

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 697602067    | Photolog    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094755">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094755</a> |