

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2023

Submitted Date:

04/21/2023

Document Number:

690204109

FIELD INSPECTION FORM

 Loc ID 325172 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10679
 Name of Operator: LOGOS OPERATING LLC
 Address: 2010 AFTON PLACE
 City: FARMINGTON State: NM Zip: 87401
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Vanessa Fields		vfields@logosresourcesllc.com	
LOGOS		regulatory@logosresourcesllc.com	
COGCC Enforcement		dnr_cogccenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214194	WELL	PR	01/01/2022	GW	067-05515	BONDAD 33-9 5	RI

General Comment:

This is a follow up of the previous reclamation inspections and in regard to NOAV #403104417.
 The corrective action of the previous inspections has not been completed.
 See attached photos and additional details within this report.

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator submitted the stormwater management plan on 8/4/2022. The plan has yet to be implemented and the previous corrective action has not been completed. The containment around the open top tank has not been reinstalled per the plan specs. There are signs of scouring of the adjacent road and no BMP's have been installed to address offsite sediment movement. Stormwater management must be designed, implemented, and maintained according to good engineering practices which may require further actions beyond the scope of the plan. Corrective action must be completed immediately.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
The Florida River is flowing very high from runoff and there is significant potential for flooding at the wellsite. Corrective action must be addressed immediately.	CostaR	04/21/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403380471	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6089667
690204111	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6089666