

Inspection Photos

API: 071-06539

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/27/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06539 | Date: 4/27/2023

Inspection Photos



Photo 1. Facing northeast at the access road. Stormwater is directed all the way down the roadside causing erosion of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06539 | Date: 4/27/2023

Inspection Photos



Photo 2. This culvert is filled in with sediment and there were no other culverts observed . Stormwater is all the way down the roadside causing erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06539 | Date: 4/27/2023

Inspection Photos



Photo 3. Facing back southeast along the access road. There is erosion along the roadside and stormwater is not diverted and runs down the entire length of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06539 | Date: 4/27/2023

Inspection Photos



Photo 4. Facing northwest along the access road. Shovel placed in erosion channel for scale.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06539 | Date: 4/27/2023

Inspection Photos



Photo 5. Facing southwest at the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06539 | Date: 4/27/2023

Inspection Photos



Photo 6. Facing west at the location. Sign is posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06539 | Date: 4/27/2023