

# Final Reclamation and Stormwater Inspection

Date: 04/20/2023

Operator: ST CROIX OPERATING INC - 81490

Location ID: 317374

Inspection Document #: 708200192

Washington County, CO

NENE Section 18 T3S R49W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Hickert 41C-18349  
Location ID: 317374



**Photo 1.** It does not appear the access/lease road has been reclaimed or contoured to reflect pre-disturbance conditions with rutting evident.

Inspection Photos  
Location Name: Hickert 41C-18349  
Location ID: 317374



**Photo 2.** Debris and equipment remain on location and will need to be removed to meet Rule 1004 standards for final reclamation. Refer to inspection report for additional information.

Inspection Photos  
Location Name: Hickert 41C-18349  
Location ID: 317374



**Photo 3.** Russian thistle and kochia debris observed within the fenced off portion of the location. Red circle is only an example as undesirable plant species were observed throughout the location. Perimeter fencing around the former skim pit is considered debris and needs to be removed.

Inspection Photos  
Location Name: Hickert 41C-18349  
Location ID: 317374



**Photo 4.** Cattle panel observed near the location; this is now considered debris and will need to be removed.

Inspection Photos  
Location Name: Hickert 41C-18349  
Location ID: 317374



**Photo 5.** Final reclamation area does not appear to be progressing towards reclamation standards with evidence of non-uniform vegetation cover resulting in areas of exposed/bare soil. Additional reclamation activities will need to be performed to meet Rule 1004 standards.

Inspection Photos  
Location Name: Hickert 41C-18349  
Location ID: 317374



**Photo 6.** Red arrow illustrates approximate well location. See comments in Photo 5.

Inspection Photos  
Location Name: Hickert 41C-18349  
Location ID: 317374



**Photo 7.** Facing east from the lease road entrance. Photo illustrates that the access road does not appear to have been reclaimed and is not progressing towards final reclamation standards. Also pictured, equipment (e.g. fencing) remains around the former tank battery location.

Inspection Photos  
Location Name: Hickert 41C-18349  
Location ID: 317374



**Photo 8.** Facing southeast at the tank battery location. No evidence of germination was observed within the reclaimed area. Further reclamation activities will need to be conducted in order for the location to meet final reclamation requirements.