

CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location # 322468



Location – Photo #02628



Location – Photo #02634

CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location # 322468




Location – Photo #02639



Wellhead – Photo #02635

CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location # 322468



Separator – Photo #02638



Tank Battery – Photo #02639




CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location # 322468



Holes in Produced Water Tank – Photo #02631



Holes in Produced Water Tank – Photo #02632

CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location # 322468



Unmarked Anchor – Photo #02637



Rill Erosion/Transport of Sediment from Location – Photo #02633

CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location # 322468



Erosion/Transportation of Sediment from Access Road – Photo #02642



Insufficient BMPs to Minimize Sediment Transportation from Access Road – Photo #02647

CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location # 322468



Insufficient Vehicle Tracking BMP – Photo #02648



Insufficient Vehicle Tracking BMP – Photo #02649