



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	unused meter box and transformer		
Corrective Action:	Comply with Rule 606	Date:	10/17/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	steel pipe and angle iron		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ancillary equipment has steel pipe and round stock		
Corrective Action:		Date:	

**Equipment:**

Type		#		corrective date
Bradenhead		# 1		
Comment:	appears plumbed to surface			
Corrective Action:			Date:	
Prime Mover		# 1		
Comment:	electric motor			
Corrective Action:			Date:	
Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Ancillary equipment		# 1		
Comment:	Electric panel, Meter box and transformers, 1 meter box and transformer not being used.			
Corrective Action:			Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 245730 Type: WELL API Number: 123-13525 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 01/24/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday 4/25/2023 at approximately 1230 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:                      Operator: KP Kauffman                      Location: Harry Ewing C #1                      API #05-123-13525                      County: Weld.                      While there, I observed a wellsite, SI at the time of inspection.                      During this inspection the following compliance issue has been documented and with a CA since 10-17-2019 and has not been addressed:                      606/ Unused equipment: unused electric transformers and meter box, CA date 10/17/2019.                      Location is dry, weather is clear, windy.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	04/25/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403384275	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093457">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093457</a>
702401885	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093446">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093446</a>